

On June 10, 2000, I appointed a Type B Accident Investigation Board to investigate the June 27, 2000. Handord Site Fire in Richland, Washington. The Board's responsibilities have been completed with respect to this investigation. The analysis, identification of contributing and root causes, and judgments of need reached during the investigation were performed in accordance with DOE O 225.1A. Accident Investigations.

I accept the report of the Board and authorize release of this report for general distribution.

Keith A. Klein Manager

U.S. Department of Friendy Richland Operations Office

This report is an independent product of the Type B Accident Investigation Board appointed by Keith A. Klein, U.S. Department of Friengy, Richland Operations Office, Richland, Washington.


The Board was appointed to perform a Type B investigation of this position and to prepare an investigation report in accordance with DOE O 225 LA, Accident Investigations.

The discussion of facts, as determined by the Board, and the views expressed in the report do not assume and are not intended to establish the existence of any duty at law on the part of the U.S. Government, its employees or agents, or subcontractors at any tier, or any other party.

This report neither determines nor implies liability.

## Type B Accident Investigation

## U.S. Department of Energy Response to the 24 Command Wildland Fire on the Hanford Site — June 27-July 1, 2000



October 2000



Fire destruction at accident scene